	er ID 67708 29, 2011 1:07:28 P	M										Page 1
Item ID: Revision ID:	D3272-1		A	Accept					Setup	Start		
Item Name:	Step									Stop		
Start Date: Required Date: Reference:		t Qty: 10.00 d Qty: 10.00			Cust Item   Customer:	ID:						
Approvals:	Process Plan:	<u>ll</u>	Date://-0329	Tooling: SPC (Y/N):		ate:			Run	Start Stop		
Sequence ID/ Work Center II	Oper D Descr	ation iption		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision N	br										
D3272	Rev B											
100	Large 1	Fab _		0.00	A	Æ		10		0_	il.	04.25
Large Fab Large Fab		Memo ***SQUARE	E ONE END BEFORE CUT	0.00 TING OTHER END**	·*							•
		1-Cut D2622 table setup D	2-120 extrusion to 116.25" lo FT 8185-2A	ong as per Dwg D3272	using cutting							
		2-Drill extrus	sion as per Dwg D3272 usin	g Jig DT8680 for rivet	ts.							
		3-Deburr	•									
110	QC6-1	nspect dimensions	to drawing	0.00								

Memo

Quality Control

D	art	Δ	er	O	SI	าล	C	P	Ιt	d	
_		_		v	~	Ju.	•	_	_	•	

		<del></del>							
W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQA	<b>\:</b>	_ Date: _	
	Re	esolution:	Disposition	on:	_ QA: N/C CI	osed:		Date: _	
NCR:		V	VORK ORD	ER NON-CONFORM	ANCE (NCR	)			
DATE	STEP	Description of NC	1		ion B Sign &	Verific	ation	Approval	Approval
	J	Section A	Initial Chief Eng	Action Description Chief Eng	Date	Section	on C 	Chief Eng	QC inspector
			·						
	·								
				•					

### Work Order ID 67708

Tuesday, March 29, 2011 1:07:28 PM



Page 2

Item ID:

D3272-1

Accept

Setup Start



**Revision ID:** 

Start Date:

Item Name:

Step

3/29/2011

**Start Qty: 10.00** 

Reg'd Qty: 10.00



Cust Item ID:

**Customer:** 

Tool ID

Reference:

Approvals:

Required Date: 4/15/2011

Process Plan:

Date:

Tooling:

Date:

Run

Start Stop

Stop



QC:

Date:

SPC (Y/N):

Set Up/

Date:

Tool # Plan

Code

Reject

Number

Insp. Stamp

Sequence ID/ Work Center ID

120

Packaging

Operation Description

Identify as per dwg & Stock Location: WA

Run Hours

0.00

0.00

M11.04.25

Accept

Qty

Reject

Qty

Packaging

130

OC

Quality Control

QC21- Final Inspection - Work Order Release

Memo

Memo

0.00

0.00

11/04/26 A)

W/O:	-		W	ORK ORDER CHANG	GES			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		-						
								1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Part No		PAR #:						
	Res	olution:					Date: _	
NCR:		·	WORK ORD	ER NON-CONFORM	ANCE (NCR)	)	•	
DATE	STEP	Description of NC			tion B	Verification	Approval	Approval
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		•						
								,
		·						
	,							

# **Picklist Print**

Tuesday, March 29, 2011 1:07:34 PM

Work Order ID: 67708

Parent Item:

D3272-1

Parent Item Name: Step



Start Date: 3/29/2011

Required Date: 4/15/2011

Page 1

**Start Qty: 10.00** 

Required Qty: 10.00

Comments:

IPP Rev:A

New Issue 07-06-09 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2622-120C		Manufactured	No			100	Each	34.0000		10	11 - 54	. 25	


Step Extrusion

Location		Loc Qtv	Loc Code	
	B66970 _	30		10
_	64409	30		***************************************
WA		4		
	46910	2		
	64409	2		

W/O:	-		W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CH	ANGE	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
×1 4111					-					
					Ę I					
٠			,							
Part No	*	PAR #:	Fault Cate	egory:	NCR:	Yes N	o <b>DQ</b>	A:	Date:	···
	Re	esolution:	Disposition	on:	QA: N	/C Clos	sed:		Date: _	
NCR:		,	WORK ORE	ER NON-CONFORM	IANCE (	NCR)				_
DATE	0750	Description of NC			ction B		Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	\$	Sign & Date		ion C	Chief Eng	QC Inspector
					· •					1



Γ	DESIG	"p	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAI	
Г	CHECK	SED	APPROVED	DRAWING NO.	REV. B
١	2	2	世	D3272	SHEET 1 OF 3
Γ	DATE			TITLE	SCALE
	07.0	5.18		STEP ASSEMBLY, HI LONG	NTS
	Α		04.03.01	NEW ISSUE	
	В		07.05.18	D3272-1 WAS D2622-120	



QTY	QTY		
-041	-042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	X	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET
10	10	101320000AD4004	NIVEI

# <u>B</u>

#### **GENERAL NOTES:**

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
  POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005.4.3
  BLACK ANTI-SKID PAINT PER DART QSI 005.4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.

SHOP COPY

RETURN TO

ENGINEERING

UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE

WORK ORDER

DII-03-29

Copyright 2004 by DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:	-		W	ORK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
								-	
								-	
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
	R	esolution:	Dispositio	n:	QA: N/C C	losed:		Date: _	
NCR:		•	WORK ORD	ER NON-CONFORM	ANCE (NCI	₹)			
DATE	STEP	Description of NC			tion B	Verific	cation	Approval	Approval
JA:-	J	Section A	Initial Chief Eng	Action Description Chief Eng	Date		ion C	Chief Eng	QC Inspector
				•					

W/O:			W	ORK ORDER CHANG	GES					·
DATE	STEP	PRO	OCEDURE CH	ANGE	В	By Date Qty Approva Chief Eng / Prod Mgr				
			·							
		·		·						
								-		
Part No	:	PAR #:	Fault Cat	egory:	NCR:	Yes N	lo DQA	<b></b>	Date:	
	R	esolution:	Dispositi	on:	QA: N/	C Clos	sed:		Date: _	······
NCR:			WORK ORE	DER NON-CONFORM	ANCE (I	VCR)				annannannannannannannannannannannannann
DATE	STEP	Description of NC			tion B		Verific	ation	Approval	Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	S	ign & Date	Section	on C	Chief Eng	QC Inspector
										·
							×			



DESIGN	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CAI	
CHECKED	APPROVED	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE		TITLE	SCALE
07.05.18		STEP ASSEMBLY, HI LONG	1:20



Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

		<del></del>									
W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			,								
									ĝi i		
					,				***************************************		
Part No		PAR #:	AR #: Fault Category:			NCR: Yes No DQA: Date:					
	R	esolution:	Disposition:			QA: N/C Closed:			Date: _		
NCR:		- 1	WORK ORDE	R NON-CONFORM	ANCE	(NCR)	.*		- — — — — — — — — — — — — — — — — — — —		
DATE	0	Description of NC	Corrective Action Se		tion B	Verific		ation	tion Approval	Approval	
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector	
							,			1,000	
						+				700000000000000000000000000000000000000	
							1.5 m				
			1								